



| Forma | D   | X   | U  | H                  | T  | E  | K  | J  |
|-------|-----|-----|----|--------------------|----|----|----|----|
| 12V9  | 50  | 1,5 | 6  |                    | 20 | 8  | 20 | 28 |
| 12V9  | 50  | 2   | 6  |                    | 20 | 8  | 20 | 28 |
| 12V9  | 75  | 1,5 | 6  |                    | 20 | 8  | 40 | 35 |
| 12V9  | 75  | 1,5 | 8  |                    | 20 | 8  | 40 | 35 |
| 12V9  | 75  | 2   | 6  |                    | 20 | 8  | 39 | 35 |
| 12V9  | 75  | 2   | 8  |                    | 20 | 8  | 39 | 35 |
| 12V9  | 75  | 3   | 6  |                    | 20 | 8  | 37 | 35 |
| 12V9  | 75  | 3   | 8  |                    | 20 | 8  | 37 | 35 |
| 12V9  | 100 | 1,5 | 6  | Diámetro a indicar | 22 | 10 | 64 | 56 |
| 12V9  | 100 | 1,5 | 8  |                    | 22 | 10 | 64 | 56 |
| 12V9  | 100 | 2   | 6  |                    | 22 | 10 | 63 | 56 |
| 12V9  | 100 | 2   | 8  |                    | 22 | 10 | 63 | 56 |
| 12V9  | 100 | 3   | 6  |                    | 22 | 10 | 61 | 56 |
| 12V9  | 100 | 3   | 8  |                    | 22 | 10 | 61 | 56 |
| 12V9  | 125 | 1,5 | 6  |                    | 25 | 10 | 79 | 75 |
| 12V9  | 125 | 1,5 | 10 |                    | 25 | 10 | 79 | 75 |
| 12V9  | 125 | 2   | 6  |                    | 25 | 10 | 78 | 75 |
| 12V9  | 125 | 2   | 10 |                    | 25 | 10 | 78 | 75 |
| 12V9  | 125 | 3   | 6  |                    | 25 | 10 | 76 | 75 |
| 12V9  | 125 | 3   | 10 |                    | 25 | 10 | 76 | 75 |

## Ejemplo de pedido

| Forma | D  | W | U | H  | Concentración | Grano | Agglomerante |
|-------|----|---|---|----|---------------|-------|--------------|
| 12V9  | 75 | 2 | 8 | 15 | C75           | D91   | *RD H        |

Otras medidas sobre demanda

\* Ver páginas 7 y 8