


Forma	D	X	H	T
1A1	20			3
1A1	20			4
1A1	20			5
1A1	20			6
1A1	20			8
1A1	20			10
1A1	25			3
1A1	25			4
1A1	25			5
1A1	25			6
1A1	25			8
1A1	25			10
1A1	30			3
1A1	30			4
1A1	30	2-3-4		5
1A1	30			6
1A1	30			8
1A1	30			10
1A1	40			3
1A1	40			4
1A1	40			5
1A1	40			6
1A1	40			8
1A1	40			10
1A1	50			3
1A1	50			4
1A1	50			5
1A1	50			6
1A1	50			8
1A1	50			10

Forma	D	T	X	H	Concentración	Grano	Aglomerante
1A1	50	8	4	20	C75	D91	*RD H

Ejemplo de pedido

Otras medidas sobre demanda

* Ver páginas 7 y 8




Forma	D	U	X	H	T	J
14A1	60	3			6	40
14A1	60	4			6	40
14A1	60	5			6	40
1A1	60				8	
1A1	60				10	
1A1	60				12	
14A1	75	3			6	50
14A1	75	4			6	50
14A1	75	5			6	50
1A1	75				8	
1A1	75				10	
1A1	75				12	
14A1	100	3			8	70
14A1	100	4			8	70
14A1	100	5	2-3-4		8	70
14A1	100	6			8	70
1A1	100			Diámetro a indicar	8	
1A1	100				10	
1A1	100				12	
14A1	125	4			8	100
14A1	125	5			8	100
14A1	125	6			8	100
1A1	125				8	
1A1	125				10	
1A1	125				12	
1A1	125				15	
14A1	150	4			10	120
14A1	150	5			10	120
14A1	150	6			10	120

Ejemplo de pedido

Forma	D	U	X	H	T	Concentración	Grano	Aglomerante
1A1	100	-	4	32	10	C75	D91	*RD H
14A1	150	6	3	32	10	C100	D64	*MD H

Otras medidas sobre demanda

* Ver páginas 7 y 8




Forma	D	U	X	H	T	J
14A1	150	8			10	120
1A1	150				10	
1A1	150				12	
1A1	150				15	
1A1	150				20	
14A1	175	4			10	140
14A1	175	5			10	140
14A1	175	6			10	140
14A1	175	8			10	140
1A1	175				10	
1A1	175				12	
1A1	175				15	
1A1	175				20	
14A1	200	5			10	160
14A1	200	6			10	160
14A1	200	8			10	160
1A1	200		2-3-4		10	
1A1	200				12	
1A1	200				15	
1A1	200				20	
14A1	250	5			15	200
14A1	250	6			15	200
14A1	250	8			15	200
14A1	250	10			15	200
14A1	250	12			15	200
1A1	250				15	
1A1	250				20	
1A1	250				30	
1A1	250				40	
14A1	300	6			15	250
14A1	300	8			15	250
14A1	300	10			15	250

Forma	D	U	X	H	T	Concentración	Grano	Aglomerante
1A1	250	-	4	127	20	C75	D91	*RD H
14A1	250	6	3	127	15	C100	D64	*MD H

Ejemplo de pedido

Otras medidas sobre demanda

* Ver páginas 7 y 8



Forma	D	U	X	H	T	J
14A1	300	12			15	250
1A1	300				15	
1A1	300				20	
1A1	300				30	
1A1	300				40	
1A1	300				60	
14A1	350	6			20	300
14A1	350	8			20	300
14A1	350	10			20	300
14A1	350	12			20	300
14A1	350	15			20	300
1A1	350				20	
1A1	350				30	
1A1	350				40	
1A1	350				50	
14A1	400	8			20	300
14A1	400	10	2-3-4	Diámetro a indicar	20	300
14A1	400	12			20	300
14A1	400	15			20	300
1A1	400				20	
1A1	400				30	
1A1	400				40	
1A1	400				60	
14A1	450	10			20	300
14A1	450	15			20	300
1A1	450				20	
1A1	450				25	
1A1	450				30	
1A1	450				40	
14A1	500	15			25	400
14A1	500	20			25	400
1A1	500				25	
1A1	500				30	

Ejemplo de pedido

Forma	D	U	X	H	T	Concentración	Grano	Aglomerante
1A1	450	-	4	127	20	C75	D91	*RD H
14A1	500	15	3	127	25	C100	D64	*MD H

Otras medidas sobre demanda

* Ver páginas 7 y 8