



Forma	D	W	X	H	T-X	E	K	J
15A2	50	3			20	10	21	27
15A2	50	4			20	10	21	27
15A2	50	5			20	10	21	27
15A2	75	4			20	10	35	43
15A2	75	5			20	10	35	43
15A2	75	6			20	10	35	43
15A2	75	8			20	10	35	43
15A2	100	4			20	10	40	52
15A2	100	5			20	10	40	52
15A2	100	6			20	10	40	52
15A2	100	8			20	10	40	52
15A2	100	10			20	10	40	52
15A2	125	4			23	10	55	70
15A2	125	5	2-3-4	Diámetro a indicar	23	10	55	70
15A2	125	6			23	10	55	70
15A2	125	8			23	10	55	70
15A2	125	10			23	10	55	70
15A2	125	12			23	10	55	70
15A2	150	4			23	10	60	80
15A2	150	5			23	10	60	80
15A2	150	6			23	10	60	80
15A2	150	8			23	10	60	80
15A2	150	10			23	10	60	80
15A2	150	12			23	10	60	80
15A2	175	5			23	10	65	85
15A2	175	6			23	10	65	85
15A2	175	8			23	10	65	85
15A2	175	10			23	10	65	85

Ejemplo de pedido

Forma	D	W	X	H	Concentración	Grano	Aglomerante
15A2	100	4	2	20	C75	D91	*RD H

Otras medidas sobre demanda

* Ver páginas 7 y 8