


Forma	D	T	X	Y	Y1	L2	L1
1A1W	3	4	0,75	3	1,5	6	50
1A1W	3	5	0,75	3	1,5	6	50
1A1W	4	4	1	3	2	6	50
1A1W	4	6	11	3	2	6	50
1A1W	5	5	1	3	3	8	50
1A1W	5	6	1	3	3	8	50
1A1W	5	5	1,5	3	3	8	50
1A1W	5	6	1,5	3	3	8	50
1A1W	6	6	1,5	6	3	10	60
1A1W	6	8	1,5	6	3	10	60
1A1W	7	6	1,5	6	4	10	60
1A1W	7	8	1,5	6	4	10	60
1A1W	7	6	2	6	3	10	60
1A1W	7	8	2	6	3	10	60
1A1W	8	6	2	6	4	10	60
1A1W	8	8	2	6	4	10	60
1A1W	8	10	2	6	4	10	60
1A1W	9	6	2	6	5	10	60
1A1W	9	8	2	6	5	10	60
1A1W	9	10	2	6	5	10	60

Forma	D	T	X	Y	Concentración	Grano	Aglomerante
1A1W	8	8	2	6	C100	D126	*RD H

Ejemplo de pedido

Otras medidas sobre demanda

* Ver páginas 7 y 8



Forma	D	T	X	Y	L1
1A1W	10	6	2	6	60
1A1W	10	8	2	6	60
1A1W	10	10	2	6	60
1A1W	12	6	2	6	60
1A1W	12	8	2	6	60
1A1W	12	10	2	6	60
1A1W	14	8	2	6	60
1A1W	14	10	2	6	60
1A1W	14	12	2	6	60
1A1W	15	8	2	6	60
1A1W	15	10	2	6	60
1A1W	15	12	2	6	60
1A1W	16	8	2	6	60
1A1W	16	10	2	6	60
1A1W	16	12	2	6	60
1A1W	18	8	2	6	60
1A1W	18	10	2	6	60
1A1W	18	12	2	6	60

Ejemplo de pedido

Forma	D	T	X	Y	Concentración	Grano	Agglomerante
1A1W	18	8	2	6	C100	D126	*RD H

Otras medidas sobre demanda

* Ver páginas 7 y 8