



Forma	D	W	X	H	E=T-X	J
4A2	75	3			6	38
4A2	75	4			6	38
4A2	75	5			6	38
4A2	75	6			6	38
4A2	100	3			8	48
4A2	100	4			8	48
4A2	100	5			8	48
4A2	100	6			8	48
4A2	100	8			8	48
4A2	125	4			10	58
4A2	125	5			10	58
4A2	125	6			10	58
4A2	125	8			10	58
4A2	125	10			10	58
4A2	150	4			10	83
4A2	150	5			10	83
4A2	150	6			10	83
4A2	150	8			10	83
4A2	150	10			10	83
4A2	175	5			12	93
4A2	175	6			12	93
4A2	175	8			12	93
4A2	175	10			12	93
4A2	200	6			14	103
4A2	200	8			14	103
4A2	200	10			14	103
4A2	200	12			14	103

1,5-2-3-4

Diámetro a indicar

Ejemplo de pedido

Forma	D	W	X	H	Concentración	Grano	Agglomerante
4A2	100	4	2	13	C75	D91	*RD H

Otras medidas sobre demanda

* Ver páginas 7 y 8