



Forma	D	X	U	H	T	E	K
6A9	75	1,5	6		25	10	60
6A9	75	1,5	10		25	10	60
6A9	75	2	6		25	10	60
6A9	75	2	10		25	10	60
6A9	75	3	6		25	10	60
6A9	75	3	10		25	10	60
6A9	75	4	6		25	10	60
6A9	75	4	10		25	10	60
6A9	100	1,5	6		30	10	82
6A9	100	1,5	10		30	10	82
6A9	100	2	6		30	10	82
6A9	100	2	10		30	10	82
6A9	100	3	6	Diámetro a indicar	30	10	82
6A9	100	3	10		30	10	82
6A9	100	4	6		30	10	82
6A9	100	4	10		30	10	82
6A9	125	1,5	6		30	10	107
6A9	125	1,5	10		30	10	107
6A9	125	2	6		30	10	107
6A9	125	2	10		30	10	107
6A9	125	3	6		30	10	107
6A9	125	3	10		30	10	107
6A9	125	4	6		30	10	107
6A9	125	4	10		30	10	107
6A9	150	2	6		35	10	130
6A9	150	2	10		35	10	130
6A9	150	3	6		35	10	130
6A9	150	3	10		35	10	130
6A9	150	4	6		35	10	130
6A9	150	4	10		35	10	130

Forma	D	W	U	H	Concentración	Grano	Aglomerante
6A9	100	4	2	13	C75	D91	*RD H

Ejemplo de pedido

Otras medidas sobre demanda

\* Ver páginas 7 y 8